



**Project:** Desert Joy 1 kas 2 - Changing foil

**Type of greenhouse:** Greenhouse

**Service:** Kas 2: covered the entire roof in the area of 5ha (ie replaced the foil on the roof: 192 foils on the sides of the roof and 96 foils on the center of the roof - total of 288 foils on the roof; 9 foils were replaced on gables) - total of 297 foils on Kas 2

Kas 3: 32 foils replaced on gables of the greenhouse (both gables)

Foils replaced on the side of the greenhouse behind the canteen in corridor at KAS 1

Foils on the roof of the corridor replaced, 12 on the sides and 6 in the center - a total of 349 foils and the whole roof painted on KAS 2, Repairing 10 platforms

**Location:** Gabes, Tunisia

This document confirms that our respectful client, Agrocare, would like to extend their appreciation for the work well done by Agrikol company on the abovementioned project and that they would highly recommend Agrikol for their professional communication, excellent construction skills and solutions, required organization, speed and work efficiency, business management and cooperation with the client. By signing this document, the client agrees that the logo of their company and their testimonial is allowed to stand on Agrikol's website as a recommendation of Agrikol's services, filed on the page Our Satisfied Clients.

*Plastic on Kas 3 looks to lose. Most probably is it because of plastic quality  
overviewed by Mr Alaa and Boris.  
We both agreed on to leave it as it is.  
And if issues with damage shows up in near future Agrikol commits  
to re-tight everything and see with it solve issue.*

*Alaa Edkine*  
\_\_\_\_\_  
(Client's representative)

*26.08.2021*  
\_\_\_\_\_  
date

*Bojan*  
\_\_\_\_\_  
(Agrikol representative)

### Address

Stefana Dečanskog 5,  
37000 Kruševac, Serbia

### Keep in Touch

T: +381 37 20 69 71  
M: office@agrikol.rs  
info@agrikol.rs

### On the Web

www.agrikol.rs